

2000-2001 A4 ,A6 2.8 ENGINE (ATQ)

Supersedes Technical Service Bulletin Group 26 number 05-03 dated July 20, 2005 due to addition of Saga warranty data, change in VIN range, and reformatting

RVU - Update Programming For Catalytic Converter System (IC)

MODELS AFFECTED:

2000 A4 VIN RANGE 203825-210716 2001 A4 VIN RANGE 000174-005064 2000 A6 VIN RANGE 001762-138397 2001 A6 VIN RANGE 001750-006884

2.8 ENGINES (ATQ)

Update programming required to eliminate possible DTC'S caused by the On Board Diagnostic For the catalytic converter system, which is too sensitive and sets DTC codes without a defect in the Catalyst system.

Vehicle must meet all of the following criteria:

- 1. Procedure is valid only for vehicles that show the IC code in the ElsaWeb Campaign/Action Information screen on the day of repair.
- 2. Vehicle must be within the Federal Emissions Warranty.
- 3. Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- 4. Procedure must be performed on applicable vehicles in Dealer inventory prior to sale.

Update Programming required to eliminate possible DTCs caused by the On Board Diagnosis OBD for the Catalytic Converter system which is too sensitive and sets fault codes without a defect in the catalyst system.

Note: Any Update Programming procedure (flash) may overwrite any tuned ECM or TCM programming. A tuned ECM or TCM is described as any ECM or TCM altered so as to perform outside the normal parameters and specifications approved by Audi of America, Inc.

Current Tuned ECM or TCM Requirements

If you encounter a vehicle with a tuned ECM or TCM, your dealership must do the following before performing any procedure that updates ECM or TCM programming: ^

Notify the owner that their ECM or TCM was found to have been tuned.

Notify the owner that any damage caused by the tuning of the ECM or TCM (including any adverse emissions consequences) will not be covered by warranties.