



TOYOTA RAV4/HIGHLANDER 2001- 2003

TOYOTA/LEXUS 60I 2792 V

2002

2001

2002

2003

RAV4/ Highlander

MIL illumination can occur for catalytic converter from DTC P0420/P430 due to improper program logic in Engine Control Module (ECM) and early deterioration of oxygen storage capacity in the catalytic converter.

Remedy: Toyota initiated a Special Service Campaign to reprogram the program logic in ECM with improved logic at a Toyota dealership. All owners were notified for this no charge reprogramming. Customers may request reimbursement, if they have previously paid for the program update or, in the rare instance, the replacement of the Catalytic Converter for this specific condition prior to receiving the owner letter