



& Exhaust Warehouse

SUBARU OUTBACK 2004

SUBARU #WWX-08 2704 V 6/9/2006 2004 Legacy, Outback Some 2004 CA Partial Zero Emission Vehicle (PZEV) certified

Subaru Legacy /Outback 2.5L NA models will experience MIL illumination and the storage of DTC P0420 (catalyst system efficiency below threshold). The P0420 illumination condition has been confirmed to be from a unique mixture of excess fuel supply and air that reacts in the catalytic converter resulting in abnormal catalyst degradation.

Remedy: SUBARU is conducting a customer service campaign. The repair will include reprogramming the ECM; and possibly catalytic converter replacement, but only if DTC P0420 is present